



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB0 (S1)  
Date: June 16, 2003  
Time: 10:55 AM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
116 N. Huey Street.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB0 (S1)  
Date: June 16, 2003  
Time: 10:55 AM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
116 N. Huey Street.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB1 (S2)  
**Date:** June 16, 2001  
**Time:** 11:30 AM  
**Weather:** Warm, sunny  
**Photo By:** Trevor Fuller  
**Description:** Surface soil sample taken from  
2227 Linden Ave.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB1 (S2)  
**Date:** June 16, 2001  
**Time:** 11:30 AM  
**Weather:** Warm, sunny  
**Photo By:** Trevor Fuller  
**Description:** Surface soil sample taken from  
2227 Linden Ave.




**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB2 (S3)  
**Date:** June 16, 2003  
**Time:** 11:45 AM  
**Weather:** Warm, sunny  
**Photo By:** Trevor Fuller  
**Description:** Surface soil sample taken from  
2415 Lawton Street.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB2 (S3)  
**Date:** June 16, 2003  
**Time:** 11:45 AM  
**Weather:** Warm, sunny  
**Photo By:** Trevor Fuller  
**Description:** Surface soil sample taken from  
2415 Lawton Street.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB3 (S4)  
Date: June 16, 2001  
Time: 12:15 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
435 S. Brookfield.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB3 (S4)  
Date: June 16, 2001  
Time: 12:15 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
435 S. Brookfield.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB4 (S5)  
Date: June 16, 2003  
Time: 12:30 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
445 Warren Street.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB4 (S5)  
Date: June 16, 2003  
Time: 12:30 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
445 Warren Street.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB5 (S6)  
**Date:** June 16, 2001  
**Time:** 12:55 PM  
**Weather:** Warm, sunny  
**Photo By:** Dan Chesterson  
**Description:** Surface soil sample taken from  
433 South Phillips.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB5 (S6)  
**Date:** June 16, 2001  
**Time:** 12:55 PM  
**Weather:** Warm, sunny  
**Photo By:** Dan Chesterson  
**Description:** Surface soil sample taken from  
433 South Phillips.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB6 (S7)  
Date: June 16, 2003  
Time: 2:30 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
2517 West Orange Street.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB6 (S7)  
Date: June 16, 2003  
Time: 2:30 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
2517 West Orange Street.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB7 (S8)  
**Date:** June 16, 2001  
**Time:** 2:30 PM  
**Weather:** Warm, sunny  
**Photo By:** Trevor Fuller  
**Description:** Surface soil sample taken from  
2517 West Orange Street.




**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB7 (S8)  
**Date:** June 16, 2001  
**Time:** 2:30 PM  
**Weather:** Warm, sunny  
**Photo By:** Trevor Fuller  
**Description:** Surface soil sample taken from  
2517 West Orange Street.






**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB8 (S9)  
**Date:** June 16, 2003  
**Time:** 3:05 PM  
**Weather:** Warm, sunny  
**Photo By:** Trevor Fuller  
**Description:** Surface soil sample taken from  
706 Brookfield.




**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MB8 (S9)  
**Date:** June 16, 2003  
**Time:** 3:05 PM  
**Weather:** Warm, sunny  
**Photo By:** Trevor Fuller  
**Description:** Surface soil sample taken from  
706 Brookfield.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB9 (S10)  
Date: June 16, 2001  
Time: 3:25 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
Southeast corner of Bendix Park.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MB9 (S10)  
Date: June 16, 2001  
Time: 3:25 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
Southeast corner of Bendix Park.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC0 (S11)  
Date: June 16, 2003  
Time: 3:45 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
Park on Sussex Ave. west of Alex  
Coquillard Elementary School.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC0 (S11)  
Date: June 16, 2003  
Time: 3:45 PM  
Weather: Warm, sunny  
Photo By: Trevor Fuller  
Description: Surface soil sample taken from  
Park on Sussex Ave. west of Alex  
Coquillard Elementary School.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MC2 (S12)  
**Date:** June 16, 2001  
**Time:** 11:30 AM  
**Weather:** Warm, sunny  
**Photo By:** Dan Chesterson  
**Description:** Surface soil sample taken from  
109 Bendix Drive.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MC2 (S12)  
**Date:** June 16, 2001  
**Time:** 11:30 AM  
**Weather:** Warm, sunny  
**Photo By:** Dan Chesterson  
**Description:** Surface soil sample taken from  
109 Bendix Drive.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC3 (S13)  
Date: June 16, 2003  
Time: 11:40 AM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
126 S. Camden Street.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC3 (S13)  
Date: June 16, 2003  
Time: 11:40 AM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
126 S. Camden Street.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MC4 (S14)  
**Date:** June 16, 2001  
**Time:** 12:00 PM  
**Weather:** Warm, sunny  
**Photo By:** Dan Chesterson  
**Description:** Surface soil sample taken from  
138 South Dundee.



**Site:** LaSalle Park/Beck's Lake  
South Bend, IN  
**Sample #:** ME1MC4 (S14)  
**Date:** June 16, 2001  
**Time:** 12:00 PM  
**Weather:** Warm, sunny  
**Photo By:** Dan Chesterson  
**Description:** Surface soil sample taken from  
138 South Dundee.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC5 (S15)  
Date: June 16, 2003  
Time: 12:20 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
138 South Kentucky.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC5 (S15)  
Date: June 16, 2003  
Time: 12:20 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
138 South Kentucky.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC6 (S16)  
Date: June 16, 2001  
Time: 12:55 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
118 South Lake Street.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC6 (S16)  
Date: June 16, 2001  
Time: 12:55 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
118 South Lake Street.






Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC7 (S17)  
Date: June 16, 2003  
Time: 1:00 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
114 S. Lake Street.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC7 (S17)  
Date: June 16, 2003  
Time: 1:00 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
114 S. Lake Street.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC8 (S18)  
Date: June 16, 2001  
Time: 2:40 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
217 North Wellington.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC8 (S18)  
Date: June 16, 2001  
Time: 2:40 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
217 North Wellington.




Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC9 (S19)  
Date: June 16, 2003  
Time: 2:55 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
218 North Illinois.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MC9 (S19)  
Date: June 16, 2003  
Time: 2:55 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
218 North Illinois.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MD0 (S20)  
Date: June 16, 2001  
Time: 3:15 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
217 Kenmore.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MD0 (S20)  
Date: June 16, 2001  
Time: 3:15 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
217 Kenmore.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MD1 (S21)  
Date: June 16, 2003  
Time: 3:35 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
102 South Falcon.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MD1 (S21)  
Date: June 16, 2003  
Time: 3:35 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
102 South Falcon.



Site: LaSalle Park/Beck's Lake  
South Bend, IN  
Sample #: ME1MD2 (S22)  
Date: June 16, 2001  
Time: 3:40 PM  
Weather: Warm, sunny  
Photo By: Dan Chesterson  
Description: Surface soil sample taken from  
102 South Falcon.

